



Building Envelope

Technology Symposium

November 13-14

2017

Omni Orlando Resort ChampionsGate

Curtain Wall Failures

Karim Allana, PE, RRC, RWC

Allana Buick & Bers, Inc.

karim@abbae.com



Copyright Materials

This presentation is protected by US and International copyright laws. Reproduction, distribution, display and use of the presentation without written permission of the speaker is prohibited.

Allana Buick & Bers, Inc. 2020



ALLANA BUICK & BERS
Making Buildings Perform Better



Best Practice

Allana Buick & Bers, Inc. (ABBAE) is a Registered Provider with the American Institute of Architects Continuing Education Systems. Credit earned on completion of this program will be reported to CES Records for AIA members. Certificates of completion for non-AIA members are available on request.

This program is registered with the AIA/CES for continuing professional education. As such, it does not include content that may be deemed or construed to be an approval or endorsement by the AIA of any material of construction or any method or manner of handling, using, distributing, or dealing in any material or product. Questions related to specific materials, methods, and services will be addressed at the conclusion of this presentation.



Karim P. Allana, PE, RRC, RWC



- **Education:** B.S., Civil Engineering, Santa Clara University
- **Registration:** P.E., Civil Engineering, California, Washington, Nevada, and Hawaii
- **Certification:** Registered Roof Consultant (RRC), Roof Consultants Institute, and Registered Waterproofing Consultant (RWC)
- **Overview:**
 - CEO and Senior Principal at Allana Buick & Bers.
 - Former Turner Construction Employee (Project Engineering and Superintendent)
 - Over 37 years experience providing superior technical standards in all aspects of building technology and energy efficiency.
 - Principal consultant in forensic investigations of building assemblies, failure analysis, evaluation and design of building infrastructure and building envelope evaluation and design.
 - Expert in all aspects of building envelope technology.
 - Completed numerous new construction, addition, rehabilitation, remodel and modernization projects for public and private sector clients.
 - Specialization in siding, roofing, cement plaster, wood, water intrusion damage, window assemblies, storefronts, below grade waterproofing, energy efficiency, solar engineering and complex building envelope and mechanical assemblies.



ABBAE Firm Overview

- Allana Buick & Bers (ABBAE) is an Architectural Engineering firm specializing in Building Envelope Systems
- ABBAE is one of the 5 largest building envelope consultants in the country
- ABBAE has over 33 years of experience & over 12,500 projects
- ABBAE is also a leading Forensic Defect firm with hundreds of forensic projects (litigation)
- Locations – 16 offices across California, Nevada, North Carolina, Oklahoma, Oregon, Texas, Virginia, Washington, Colorado



Staff & In-House Expertise

- Licensed Professional Engineers – Civil, Structural, and Mechanical
- Registered Architects
- Building Enclosure Commissioning Process Providers (BECxPs)
- Registered Building Envelope Consultant (RBEC)
- Registered Roofing Consultants (RRCs)
- Registered Waterproofing Consultants (RWCs)
- Registered Exterior Wall Consultant (REWCs)
- Registered Roof Observers (RROs)
- Certified Exterior Insulation and Finish System (EIFS) inspectors
- Curtain Wall Specialists
- ICC Certified Building Inspectors
- Quality Assurance Monitors
- Water Testing Experts
- Leak Investigation and Diagnosis Experts
- Infrared Imaging and Nuclear Moisture Scanning Experts



ABBAE Building Expertise

- Building Envelope Systems
 - Roofing Systems
 - High-Slope/Low-Slope Roofs
 - Green/Garden Roofs
 - Drainage Systems
 - Pedestrian Plazas
 - Exterior Wall Systems
 - Wall Cladding/Siding/GFRC/pre-cast
 - EIFS/cement plaster/stucco
 - Sheet Metal Flashings
 - Windows and Glazing Systems
 - Punched Windows
 - Curtain Wall/Window Wall Systems
 - Sliding Glass Doors
 - Skylights
- Building Envelope Systems (cont'd)
 - Roofing & Waterproofing Systems
 - Deck/Balcony/Lanai Waterproofing
 - Podium Waterproofing
 - Pool/Spa Deck Waterproofing
 - Above-Grade/Below-Grade Waterproofing
 - All types of low and steep sloped roofing
 - Commissioning BECx
 - OPR/BOD/Commissioning Plan
- Mechanical/HVAC Systems
 - HVAC design
 - Plumbing systems
 - Commissioning and testing



ABBAE Core Services

- Consulting and third-party peer review services
- Engineer of record for building envelope systems
- Contract administration services
- Inspection services (usually direct with owner)
- Air and water performance testing
- Mock-up design, observation, and testing
- Building assessments and forensic investigations
- Litigation support and expert witness services
- Educational seminars with AIA credits



Presentation Outline

- Typical Curtain Wall Systems
- Common Modes of Failure
- Lessons Learned



Typical Curtain Wall Systems

- By definition, a wall that carries no weight other than its own
- Load transferred to the edge of the floor slab
- Panels “hang” like a curtain from structural elements
- Commonly in-filled with glass, but can be in-filled with stone veneer, metal panels, operable vents



The Hallidie Building, SF



One of the Oldest Glass
Curtain Walls (1918)



Typical Curtain Wall Systems

- Can be a stick assembly system or unitized (modular) system for prefabrication
- Oldest curtain walls were built with thick masonry and brick or terra cotta
- In theory, they can perform for decades



Stick Assembly vs. Unitized System



Common Modes of Failure

- Gasket Failure
 - Water Intrusion
 - Air infiltration
- Aluminum Coating Failure
 - Missing primers
 - Coating thickness issue
 - Contaminants
- Corrosion of Glass
 - Edge deletion issue
 - Standing water on seals
- IGU Polyisobutylene (PIB) Failure
- Aluminum Thermal Break Failure




Gasket Failure



What is a Gasket?

- Gaskets - strips of synthetic rubber compressed between the glazing and frame or frame to frame
- Generally extruded EPDM
- Can be special ordered with silicone



Gasket Failures


- Drying out, shrinking and cracking
- Exposure to UV radiation
- Exposure to freeze-thaw cycles
- Improper maintenance



Mondavi Gasket Shrinkage / Failure



Gasket Failure



Gasket Failure - San Jose Condo



Gasket Failure - San Jose Condo



Gasket Failure- San Jose Condo



Gasket Failure- San Jose Condo



Pieces of failed
gasket that have
fallen off the building



Gasket Failure- SM College Library



Gasket Failure- Causing Leaks




Gasket Failure- Causing Leaks




Leaks Through Window Glazing Seals

- “Glazing seal” refers to the seal between the glass and window sash
- Commercial windows use tape with adhesive backing on two sides and silicone heel or cap beads for glazing seals
- Fin style windows often only use acrylic tape and no wet silicone
- Acrylic tape can break down from UV and water
- In some cases window sashes can overflow with just a light spray



Glazing Gaskets Enhanced



Gasket/Seal Failure Effects

- Water intrusion
- Air infiltration
 - Energy loss
 - Condensation



Leaks Due To Gasket Shrinkage




Leaks Due To Gasket Shrinkage



Typical EPDM Mullion Gasket Shrinkage

15/16" glazing installed produces a loose seal and leaks



Gasket Shrinkage Water Intrusion




Air Infiltration Can Cause

- Air Infiltration can lead to:
 - Energy loss
 - Creating an Air Tight Enclosure Makes all the Difference
 - ASHRAE 90.1 User Manual
 - “Controlling infiltration is important to achieving energy- efficient building.”
 - Air infiltration creates additional loading on the mechanical system
 - Newer Codes (2009 IBC) will require Air Barriers and on-site testing
 - Condensation
 - Commonly mistaken for water intrusion




Condensation Due to Gasket Shrinkage




Condensation Due to Gasket Shrinkage

Condensation can
damage interior
surfaces - mold



How Condensation Can Occur



Thermal
Path

Avoiding Gasket Failure

- Specifying high quality gasketing materials
- Quality control testing/commissioning to check for specified materials
- Using wet seals on inside in conjunction with gaskets



Aluminum Coating Failure




Aluminum Coating Failure



Coating is blistering
on window sill
flashings




Aluminum Coating Failure



Coating is
peeling off
aluminum
frames



San Francisco Condo #1



Coating is bubbling
on window frames



San Francisco Condo #1



San Francisco Condo #2



San Francisco Condo #2



San Francisco Condo #2



Coating Failure Causing Pitting



Aluminum Coating Failure Causes

- Proper surface preparation and pre-treatments are not followed
 - Missing primer
- Coating requirements are not followed
 - Improper thickness of coating
- Lack of surface prep – leading to trapped contaminants



Aluminum Coating Failure Prevention

- Proper preparation and coating requirements must be followed
 - Surface preparation, coating thickness requirements
- Use of Fluoropolymer finishes that meet AAMA 2605 certification
- Reviewing coating submittals
- Performing factory visits and verification
- Obtaining samples from factory runs and send for independent testing



Corrosion of Glass



Corrosion/Tarnishing of Silver Coatings




Tarnishing of Low-E Silver Coatings



Low-E coating is failing past the primary seals causing an insulating glazing seal failure



Start of Low-E Coating Corrosion



Low-e coating corrosion is taking place at the edges of the glazing unit. Initially, this condition is not visible from the interior



Continuing Low-E Coating Corrosion





Causes of Corrosion

- Edge Deletion Failure
 - Leads to IGU glazing failure
- Standing water on top of silicone sealant



What is an Insulating Glass Unit?

- Insulating Glass Units are sealed with PIB and Silicone combinations of 2 or more lites of glass separated by a dry air space




How Are Dual Glazing Units Sealed?


Spacer, usually aluminum or stainless steel

Primary Seal (PIB)
impermeable to moisture
diffusion.


Secondary Seal (structural)
and selected to hold unit
together through long-term
weathering (UV) and
prevent water infiltration



IGU Seals, Stainless Spacers Last Longer



IGU Units Sealed With Dual Sealants




Generally IGU is sealed with both P.I.B. (for vapor resistance) and Silicone (water resistance and UV)





Low-E Coating: What is it?

- Microscopically thin and virtually invisible metal or metallic oxide layers (silver) deposited on the glass to reduce the U-factor and (SHGC) Solar heat gain by suppressing radiative heat flow.



What Edge Deletion?

- Low-E coating needs to be edge deleted. If not edge deleted, the exposed edge could start corrosion and spread to inside
- Once corrosion starts, it breaks down the seals causing overall unit failure



Edge Deletion During Manufacturing



Low-E coating has been deleted around the edges of glass to allow for IGU seals to perform better



Case Study – SF Condo



Replacing Glass, Slow and Tedious



2 guys on window
washing rigs

3 guys on the inside
handling glass



Replacing Glass, Slow and Tedious




Removed glass
from site

Labeled and crated,
shipped to lab



Water Infiltration at Head Stands on IGU Seal



Laboratory Conclusion of Failure

All IG units have low-E deleted only about 3/8" but the total bond line of the PIB and silicone is about 5/8" to 3/4"

February 21, 2017
Page 2 - Report #49780

All IG units have the low-E edge deleted about 3/8", but the total bond-line of the PIB and silicone is about 5/8" - 3/4".

Evaluation of the PIB and silicone seals does not indicate any compatibility issues. The PIB shows excellent chemical distribution when thermally analyzed by Thermo-Gravimetric Analysis (TGA) and compared to a stock PIB (see attached plot).

Energy dispersive X-ray spectroscopy (EDX) of the edge-delete (Table A), low-E coating under the PIB (Table B), and discolored low-E revealed that there was no corrosive materials such as chlorine, phosphorus, or sulfur in contact with any surfaces. There is evidence however, that the edge delete was not complete and left some residual low-E coating under the silicone secondary seal.

Table A

Element	Weight %
Carbon	8.90
Oxygen	32.78
Magnesium	1.33
Silicone	23.12
Calcium	3.55
Titanium	0.25
Zinc	20.63
Silver	4.28
Tin	5.13

Table B

Element	Weight %
Carbon	3.97
Sodium	8.68
Oxygen	32.38
Magnesium	1.29
Silicone	23.84
Calcium	4.78
Titanium	0.87
Iron	0.25
Zinc	13.53
Silver	6.04
Tin	4.09

DISCUSSION

Failure is most likely the result of extended water contact due to the flexible vertical tubing retaining water, which allowed water to migrate along the tops of the IG units. It appears there is installation issues with the lack of vertical tube drainage as well as IG manufacture by not edge-deleting properly. The PIB is of good quality and could have resisted water penetration if it were not adhered to the low-E which is attacked by the water contact, resulting in bond/seal loss.

Overall IG workmanship and material skills are satisfactory with the exception of the edge-deletion.

DALLAS LABORATORIES, INC.


Kévan W. Jones, Vice President

Analyst: KJ, GF, SL
KWJ: js



Overall IG workmanship and material skills are satisfactory with the exception of the edge deletion

Prevention

- Proper edge deletion needs to occur during the manufacturing process to ensure proper bonding of the IGU sealants
- Design of the glazing and curtain wall assembly should not allow water to stand on top of the silicone sealant because, silicone is permeable
- Design installation of glass should be on blocks and properly drained to prevent dual glazing to sit in water




Polyisobutylene (PIB) Migration




PIB Migration

- PIB (primary) and secondary sealants prevent air/ water infiltration in IGU airspace
- PIB moves from window edge, obscuring vision



PIB Migration/Failure in IGU



PIB Migration, Moving/Walking Up



PIB Migration



Case Study- SF Condo w/ PIB Migration




Case Study- SF Condo w/ PIB Migration



Case Study- SF Condo w/ PIB Migration



Case Study- SF Condo w/ PIB Migration



PIB Migration Mitigation

- Requires glazing replacement
- Limited to gray PIB
- Gray PIB contains 64.8% polymer with plasticizers as low as 2.6%
 - PIB control samples are 97.5% polymer and 30% plasticizer



Thermal Break Failure



SF Condo



SF Condo



SF Condo




Thermal Break Failure

- Can cause condensation on frame
- Aluminum frame in contact with concrete
- Occurs when thermal breaks are missing or bypassed



How Condensation Can Occur




Thermal
Breaks

Aluminum back angle in
contact with concrete;
and in contact with back
side of aluminum frame
is a thermal bridge. Both
the angle and frame are
condensing

Thermal
Path
Through
Concrete



Condensation



Thermal Break Failure-Condensation

- When the frame reaches dew point, water vapor condenses
- Condensation Resistance Factor (CRF) should match heat/humidity/building use requirements
- Modern curtain walls use thermal breaks prevent condensation



Avoiding Condensation

- Window design should include thermally broken systems
- Design considerations include:
 - Carefully design thermal breaks in and around glazing elements and rough openings in walls
 - Hygrothermal modeling to determine CRF requirements
 - Avoiding thermal bridges in design
 - Descriptive and fully illustrated perimeter flashing conditions



Lessons Learned

- Conscientious Design
 - Understanding modes of failures
 - Proper material selection of internal seals, water pathways and sealants is key
 - Specifying design issues like edge deletion, and "wet" pockets of glazing
 - Learn from new modes of failures
 - Quality control and commissioning to ensure performance
- Evaluation and Testing
 - For both new construction and remediation
 - Material testing of system sub-components such as coatings, seals, and construction



The End

