

# Building Skin Failures

**Karim Allana, PE, RRC, RWC**

Allana Buick & Bers, Inc.

karim@abbae.com



Kanton Bern  
Canton de Berne



ADVANCED  
BUILDING SKINS

# Karim P. Allana, PE, RRC, RWC

**EDUCATION:** B.S., Civil Engineering, Santa Clara University

**REGISTRATION:** P.E., Civil Engineering, California, Washington, Nevada and Hawaii

**CERTIFICATION:** Registered Roof Consultant (RRC), Roof Consultants Institute, Registered Waterproofing Consultant (RWC), Roof Consultants Institute

## **OVERVIEW:**

- CEO and Senior Principal at Allana Buick & Bers.
- Former Turner Construction Employee (Project Engineering and Superintendent)
- Over 37 years experience providing superior technical standards in all aspects of building technology and energy efficiency.
- Principal consultant in forensic investigations of building assemblies, failure analysis, evaluation and design of building infrastructure and building envelope evaluation and design.
- Expert in all aspects of building envelope technology.
- Completed numerous new construction, addition, rehabilitation, remodel and modernization projects for public and private sector clients.
- Specialization in siding, roofing, cement plaster, wood, water intrusion damage, window assemblies, storefronts, below grade waterproofing, energy efficiency, solar engineering and complex building envelope and mechanical assemblies.

# Common Modes of Failure


- Gasket Failure
  - Water Intrusion
  - Air infiltration
- Aluminum Coating Failure
  - Missing primers
  - Coating thickness issue
  - Contaminants
- Corrosion of glass
  - Edge deletion issue
  - Standing water on seals
- IGU Polyisobutylene (PIB) Failure
- Aluminum Thermal Break Failure

# Gasket Failure



# What is a Gasket?

- Gaskets - strips of synthetic rubber compressed between the glazing and frame or frame to frame
- Generally extruded EPDM
- Can be special ordered with silicone




# Gasket Failures

- Drying out, shrinking and cracking
- Exposure to UV radiation
- Exposure to freeze-thaw cycles
- Improper maintenance
- Failures experienced in 4-6 years

# Mondavi Gasket Shrinkage / Failure




# Gasket Failure





# Gasket Failure- San Jose Condo




# Gasket/Seal Failure Effects

- Water intrusion
- Air infiltration
  - Energy loss
  - Condensation

# Typical EPDM Mullion Gasket Shrinkage

15/16" glazing installed produces a loose seal and leaks



# Gasket Shrinkage Water Intrusion




# Air Infiltration Can Cause

- Air Infiltration can lead to:
  - Energy loss
  - Condensation
    - Commonly mistaken for water intrusion




# Condensation Due to Air Leakage




# Condensation Due to Gasket Failure

Condensation can  
damage interior  
surfaces - Mold



# How Condensation Can Occur



Thermal  
Path



# Avoiding Gasket Failure

- Specifying high quality gasketing materials
- Quality control testing/commissioning to check for specified materials
- Using wet seals on inside in conjunction with gaskets


# Aluminum Coating Failure

# Aluminum Coating Failure



Coating is  
blistering on  
window sill  
flashings.

# Aluminum Coating Failure



Coating is peeling off aluminum frames.

# San Francisco Condo #1



# Coating Failure Causing Pitting





# Aluminum Coating Failure Causes

- Proper surface preparation and pre-treatments are not followed
  - Missing primer
- Coating requirements are not followed
  - Improper thickness of coating
- Lack of surface prep – leading to trapped contaminants


# Corrosion of Glass



# Corrosion/Tarnishing of Silver Coatings



# Start of Low-E Coating Corrosion




Low-e coating corrosion is taking place at the edges of the glazing unit. Initially, this condition is not visible from the interior.


# What Edge Deletion?

- Low-E coating needs to be edge deleted. If not edge deleted, the exposed edge could start corrosion and spread to inside.
- Once corrosion starts, it breaks down the seals causing overall unit failure


Low-E coating is not edge deleted



Low-E coating is edge deleted



# Edge Deletion During Manufacturing






# Prevention

- Proper edge deletion needs to occur during the manufacturing process to ensure moisture does not attack edge of coating
- Design of the glazing and curtain wall assembly should not allow water to stand on top of the silicone sealant because, silicone is permeable
- Design installation of glass should be on blocks and properly drained to prevent dual glazing to sit in water


# **Insulated Glazing Unit (IGU) Polyisobutylene (PIB) Migration**

# PIB Migration

- PIB (primary) and secondary sealants prevent air/ water infiltration in IGU airspace
- PIB moves from window edge, obscuring vision



# PIB Migration/Failure in IGU






# PIB Migration, Moving/Walking Up



# Case Study- SF Condo w/ PIB Migration




# Case Study- SF Condo w/ PIB Migration




# Thermal Break Failure

# Condensation



# How Thermal Break Failure Occured



# Avoiding Condensation

- Window design should include thermally broken systems
- Design considerations include:
  - Carefully design thermal breaks in and around glazing elements and rough openings in walls
  - Hygrothermal modeling to determine CRF requirements
  - Avoiding thermal bridges in design
  - Descriptive and fully illustrated perimeter flashing conditions



# Lessons Learned

- Conscientious Design
  - Understanding modes of failures
  - Proper material selection of internal seals, water pathways and sealants is key
  - Specifying design issues like edge deletion, and „wet“ pockets of glazing
  - Learn from new modes of failures
  - Quality control and commissioning to ensure performance
- Evaluation and Testing
  - For both new construction and remediation
  - Material testing of system sub-components such as coatings, seals, and construction



# The End

