

## Maintenance and Repair Strategies

CAA Seminar – Increasing Your Property Value March 23, 2004

#### **Copyright Materials**

This presentation is protected by US and International copyright laws. Reproduction, distribution, display and use of the presentation without written permission of the speaker is prohibited.

Allana Buick & Bers, Inc. 2020



#### **Best Practice**

Allana Buick & Bers, Inc. (ABBAE) is a Registered Provider with the American Institute of Architects Continuing Education Systems. Credit earned on completion of this program will be reported to CES Records for AIA members. Certificates of completion for non-AIA members are available on request.

This program is registered with the AIA/CES for continuing professional education. As such, it does not include content that me be deemed or construed to be an approval or endorsement by the AIA of any material of construction or any method or manner of handling, using, distributing, or dealing in any material or product. Questions related to specific materials, methods, and services will be addressed at the conclusion of this presentation.



#### Karim P. Allana, PE, RRC, RWC

• Education: B.S., Civil Engineering, Santa Clara University

Registration: P.E., Civil Engineering, California, Washington,

Nevada, and Hawaii

Certification: Registered Roof Consultant (RRC), Roof Consultants

Institute, and Registered Waterproofing Consultant (RWC)

#### Overview:

- CEO and Senior Principal at Allana Buick & Bers.
- Former Turner Construction Employee (Project Engineering and Superintendent)
- Over 37 years experience providing superior technical standards in all aspects of building technology and energy efficiency.
- Principal consultant in forensic investigations of building assemblies, failure analysis, evaluation and design of building infrastructure and building envelope evaluation and design.
- Expert in all aspects of building envelope technology.
- Completed numerous new construction, addition, rehabilitation, remodel and modernization projects for public and private sector clients.
- Specialization in siding, roofing, cement plaster, wood, water intrusion damage, window assemblies, storefronts, below grade
  waterproofing, energy efficiency, solar engineering and complex building envelope and mechanical assemblies.

#### **ABBAE Firm Overview**

- Allana Buick & Bers (ABBAE) is an Architectural Engineering firm specializing in Building Envelope Systems
- ABBAE is one of the 5 largest building envelope consultants in the country
- ABBAE has over 33 years of experience & over 12,500 projects
- ABBAE is also a leading Forensic Defect firm with hundreds of forensic projects (litigation)
- Locations 16 offices across California, Nevada, North Carolina, Oklahoma, Oregon, Texas, Virginia, Washington, Colorado and Hawaii

#### Staff & In-House Expertise

- Licensed Professional Engineers Civil, Structural, and Mechanical
- Registered Architects
- Building Enclosure Commissioning Process Providers (BECxPs)
- Registered Building Envelope Consultant (RBEC)
- Registered Roofing Consultants (RRCs)
- Registered Waterproofing Consultants (RWCs)
- Registered Exterior Wall Consultant (REWCs)

- Registered Roof Observers (RROs)
- Certified Exterior Insulation and Finish System (EIFS) inspectors
- Curtain Wall Specialists
- ICC Certified Building Inspectors
- Quality Assurance Monitors
- Water Testing Experts
- Leak Investigation and Diagnosis Experts
- Infrared Imaging and Nuclear Moisture Scanning Experts

### **ABBAE Building Expertise**

- Building Envelope Systems
  - Roofing Systems
    - High-Slope/Low-Slope Roofs
    - Green/Garden Roofs
    - Drainage Systems
    - Pedestrian Plazas
  - Exterior Wall Systems
    - Wall Cladding/Siding/GFRC/pre-cast
    - EIFS/cement plaster/stucco
    - Sheet Metal Flashings
  - Windows and Glazing Systems
    - Punched Windows
    - Curtain Wall/Window Wall Systems
    - Sliding Glass Doors
    - Skylights

- Building Envelope Systems (cont'd)
  - Roofing & Waterproofing Systems
    - Deck/Balcony/Lanai Waterproofing
    - Podium Waterproofing
    - Pool/Spa Deck Waterproofing
    - Above-Grade/Below-Grade Waterproofing
    - All types of low and steep sloped roofing
  - Commissioning BECx
    - OPR/BOD/Commissioning Plan
- Mechanical/HVAC Systems
  - HVAC design
  - Plumbing systems
  - Commissioning and testing

#### **ABBAE Core Services**

- Consulting and third-party peer review services
- Engineer of record for building envelope systems
- Contract administration services
- Inspection services (usually direct with owner)
- Air and water performance testing
- Mock-up design, observation, and testing
- Building assessments and forensic investigations
- Litigation support and expert witness services
- Educational seminars with AIA credits



#### Maintenance Vs. Repairs

- Inherent construction defect requiring repairs is not maintenance!
- Identify repairs that fall outside of regular maintenance.

#### In Order to Define What Is Maintenance...

- Define life expectancy for components.
- More frequent replacement or repair = likely construction defect, not maintenance.
- Maintenance = cleaning, debris removal, etc.

#### Life Expectancies...

- Sealants: 10 to 25 years
- Painting: 5 to 7 years
- Hardboard siding: 25 years
- Roofs: 20 to 30 years
- Below grade waterproofing: Life of the building.
- Windows: Life of the building.
- Stucco: Life of the building.

#### Repairs Due To Defective Construction

- If a 20 year type roofing system needs "repairs" other than, leaf cleaning, or physical damage.
- If 20 year type (or 10 year type) sealants need replacement or fail in less than their life expectancy.
- Window leaks in less than 10 years.

#### If You Identify Defective Construction...

- Immediately notify a Supervisor or Principal of the company.
- For re-roofing, re-painting, replacement sealants, etc., 10 year construction statues may apply.
- Approach the Contractor and ask them to permanently repair or replace the problem application.

#### **New Construction Defects**

- California law holds Contractors responsible for latent defects up to maximum of 10 years from completion.
- Once a defect is known, the statue of limitation is 3 years.
- After either time period runs out, the Contractor can not be held responsible.



#### **Ongoing Roof Maintenance**

- Frequently occurring items like:
  - Gutter cleaning.
  - Annual inspection of roofs.
  - Tree trimming.
  - Repair damage from tree limbs.





#### Siding Is...

- Cement plaster (stucco).
- Window walls and other glass.
- EIFS (thin coats of stucco over foam-type material).
- Masonry (brick siding, brick veneer, etc.).
- Wood products (redwood, cedar, etc.).
- Composites (T-111, hardboard, OSB, etc.).

<sup>\*</sup> According to the National Roofing Contractors Association Roofing and Waterproofing Manual, 4th edition



## We will focus on hardboard and wood siding...

### History of Materials and Construction Methods

- Old growth wood now harder to find
- For energy purposes, buildings are tighter and do not ventilate as well
- An example of <u>ventilated old siding</u>.
- Hardboard and oriented strand board (OSB) are inferior in performance to wood, especially old growth wood.



















#### **Maintenance Tips**

- Regularly inspect and replace sealants.
- Back prime all replacement trim and wood end prime all wood.
- Redirect sprinklers away from building siding.
- Paint on a regular cycle, 3 to 5 years.
- Paint the bottom edges of siding.





### How To Recognize Problems In Siding

- Cracks and splits in siding and sealants, especially at corners and joints.
- Swelling and buckling of siding.
- Separation, due to swelling or shrinkage at windows, doors, and other opening.
- Siding problems.
- Sealant problems.
- Flashing problems.











# Sealants and Painting for Stucco and Siding

#### **Design Rules of Thumb**

- Use appropriate details.
- Specify head flashings and install properly.
- Specify and install flexible flashings and underlayments.
- Properly select trim materials and installation methods.
- Specify sealants that are appropriate for the use and installed properly.